



Bristow, Oklahoma

Northwest Corner Northeast Quarter Section 30, T. 16 N., R. 9 E., I.M.

R. 9 E.

LEGEND

- ⊙ - Power Pole
- ↑ - Guy Anchor
- ⬢ - Underground Fiber Optic Sign
- ⊕ - Fire Hydrant
- ⊕ - Water Valve
- - Bollard
- ⊙ - Sanitary Sewer Manhole
- ⊕ - Reinforced Concrete Pipe
- R & M - Record and Measured
- NTS - Not To Scale
- ⊕ - Schedule B Item Identifier
- ⊕ - Potential Encroachment Identifier
- ⊕ - Street/Parking Lot Light
- - Traffic Direction Arrow
- - Storm Sewer Inlet
- ♿ - Handicap Parking Space
- ⊕ - Natural Gas Gas Meter



POINT OF COMMENCEMENT

POINT OF BEGINNING

S.00°52'46"E.
392.06' (R & M)

R = 4643.55'
L = 113.96'
Delta = 1°24'22"
(R & M)
NTS

S.74°27'27"E.
206.81' (NTS)

R = 4613.35'
L = 270.86'
Delta = 3°21'41"
(R & M)
NTS

N.00°35'47"W.
432.19' (R & M)

OWNERS:
Collins Limited Partnership
P.O. Box 660
Bristow, Oklahoma
Acct. No. 5999-30-016-009-0-010-00

Tractor Supply Company

Proposed Premises Approx.
9,100 sf (70' x 130')

6' hallway

Building Corner is 0.33'
North of Property Line
NO ENCROACHMENT

Building Corner is 0.31'
North of Property Line
NO ENCROACHMENT

OWNERS:
Collins Limited Partnership
P.O. Box 660
Bristow, Oklahoma
Acct. No. 5999-30-016-009-0-030-00

TSC Outdoor
Display Area

OWNERS:
Jali & Davood Martazani
7951 S. 86th East Place
Tulsa, Oklahoma
Acct. No. 5999-30-016-009-0-040-00

Newly constructed
Mazzio's

Pylon

Newly constructed
McDonald's

